
Preliminary Hand-Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date

3/28/2019 5:00:00 AM to 3/28/2019 6:00:00 AM



Recent Benzene Detections

Location Category	Reading Date	Concentration
Division E	3/28/2019 05:59:23	3.040 ppm
	3/28/2019 05:57:35	1.190 ppm
	3/28/2019 05:56:59	1.110 ppm
	3/28/2019 05:54:51	4.530 ppm
	3/28/2019 05:53:22	0.350 ppm
	3/28/2019 05:48:44	0.280 ppm
	3/28/2019 05:47:18	0.190 ppm
	3/28/2019 05:44:47	0.150 ppm
	3/28/2019 05:33:24	2.000 ppm
	3/28/2019 05:31:41	0.900 ppm
	3/28/2019 05:29:56	0.650 ppm
	3/28/2019 05:08:51	0.150 ppm
Impacted Tank Farm	3/28/2019 05:50:00	0.225 ppm
	3/28/2019 05:49:50	0.450 ppm
	3/28/2019 05:45:59	0.125 ppm
	3/28/2019 05:45:47	0.750 ppm
Industrial Area	3/28/2019 05:59:51	2.025 ppm
	3/28/2019 05:52:08	0.650 ppm
	3/28/2019 05:47:11	7.000 ppm
	3/28/2019 05:44:33	1.850 ppm
	3/28/2019 05:43:32	0.200 ppm
	3/28/2019 05:42:09	0.870 ppm
	3/28/2019 05:40:45	0.200 ppm
	3/28/2019 05:39:44	4.450 ppm
	3/28/2019 05:38:48	1.650 ppm
	3/28/2019 05:30:24	1.650 ppm
	3/28/2019 05:27:53	0.175 ppm
	3/28/2019 05:26:10	1.550 ppm
	3/28/2019 05:24:38	0.175 ppm
	3/28/2019 05:17:33	2.350 ppm
	3/28/2019 05:11:39	0.150 ppm
	3/28/2019 05:07:20	0.125 ppm
	3/28/2019 05:03:15	6.975 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only